

## OUR BUSINESS SECTORS:


- MEASURE AND AGEING MACHINES
- ASSEMBLY AND MACHINING EQUIPMENT
- SUBCONTRACTING
- AUTOMATION UNITS

# Remise à zéro

CHECK OF THE HANDS HOLDING



Watch the video of the  
product on the Internet



# Remise à zéro

Check the running of the button functions

## Equipment

• This equipment enables the activation of the functions Start, Stop and Reset on watch heads and movements. It is possible to define the time between start and stop. The activation force is continuously measured and tolerance thresholds can be configured.

## Plate

• A plate system (10 or 20 positions), with quick locking and an extraction handle, ensures an easy interchangeability of the elements to test.

## Recognition

• Each plate has a specific coding that will select appropriate set up automatically.


## Presence detection

• A sensor detects the presence of movements/watches on the plate. Only positions with an element will be tested.




## Positioning ruler

• Two small positioning rulers allow the set up of the actuators in front of the button functions.



## Actuator

Three electrical actuators allow the activation of the different functions. The activation force is measured and the activation speed can be configured.



## Technical data

	10 positions version	20 positions version
Number of sensors		3
Number of positions	10	20
Max. force		60 N
Precision		+/- 20 %
Interface		Touchscreen
Connections		230 V - 100 W
Dimensions	750 x 480 x 245 (l x d x h)	900 x 700 x 250 (l x d x h)
Weight	37 kg	65 kg