


Spare parts


Indexing table TPP90


Article No	Description	Complement	Pce/unit	Former article no.
	FJ-0100.058	Repair kit: - Set of gaskets - Assembly tooling - Assembly grease	TPP90	1


	FJ-0100.057	Set of gaskets	TPP90	1
--	-------------	----------------	-------	---

In order to ensure a longer life to our products, we have made modifications. These improvements require the assembly of new gasket kits and new racks:

- The new gasket kit **FJ-0100.058** comes with the new racks ref. **7001166** and **7001167** + special grease.
- The new rack ref. **7001167** has to be used with the new nut ref. **7001171**.

Article No	Description	Complement	Pce/unit	Former article no.
	7001166	Rack (full)	TPP90	1


	7001167	Rack (hollow)	TPP90	1
---	---------	---------------	-------	---

	7001171	Nut	TPP90	1
---	---------	-----	-------	---



	Article No	Description	Complement	Pce/unit	Former article no.
	7000018	Internal shock-absorber (hard, 10.95)	TPP90	1	BP66-AI
	7000061	Internal shock-absorber (medium, 10.94)	TPP90	1	BP66-AI
	7000062	Internal shock-absorber (weak, 10.93)	TPP90	1	BP66-AI
	7100001	Complete clutch 2/4/6/8/12/18/24 positions	TPP90	1	TPP90-EM
	7100003	Complete clutch 3/15 positions	TPP90	1	TPP90-EM
	7100004	Complete clutch BI (bidirectional)	TPP90	1	TPP90-EM
	7100002	Complete shaft	TPP90	1	TPP90-A



	Article No	Description	Complement	Pce/unit	Former article no.
	JSC6-M5AT	Speed controller	TPP90	3	
	FE-00330.010	Detector PNP with connector	TPP90 TPP90 BI	2 3	
	FE-00330.020	5m-cable for detector	TPP90 TPP90 BI	2 3	
	FE-00330.030	3m-cable for detector	TPP90 TPP90 BI	2 3	
	7001090	Slotted sleeve l= 19	TPP90	1	BP66E-2014
	7001088	Slotted sleeve l= 24	TPP90	1	BP66E-1014

